±0.3°C accuracy

- CAL CHECK®
- · Stainless steel folding probe with penetration tip
- · Enables angled measurement
- Ergonomic
- · Auto shut-off

The folding Checktemp®4 provides practical temperature measurement for the food service industry.

Special attention was given to the ergonomic form of Checktemp®4. This thermometer fits comfortably and securely in your hand. The LCD on the side of the handle is easy to see and read. The fast responding, fold-away probe is made of high quality, stainless steel and can penetrate semi-frozen and semi-solid foods like meats, ice cream and cheeses. When you are finished using your Checktemp®4, wipe the probe clean and fold it away. Checktemp®4 automatically turns OFF so you can safely carry it in your pocket.

CAL CHECK®

As you unfold the stainless steel probe, the Checktemp® 4 automatically turns ON and immediately performs a calibration test. This unique HANNA feature, CAL CHECK®, provides the security of knowing you have accurate measurements. CAL CHECK® also lets you know if your battery level is low or if your meter requires recalibration.

Folding Pocket Thermometer Turns on and off by opening and closing the probe

SPECIFICATIONS	HI 151-00 (Checktemp®4C)	HI 151-01 (Checktemp®4F)
Range	-50.0 to 220°C	-58.0 to 428°F
Resolution	0.1°C (-50.0 to 199.9°C); 1°C (200 to 220°C)	0.1°F (-58.0 to 199.9°F); 1°F (200 to 428°F)
Accuracy	±0.3°C ±1 digit (-20.0 to 90.0°C); ±1% F.S. ±1 digit (outside)	± 0.5 °F ± 1 digit (-4.0 to 194.0°F); $\pm 1\%$ F.S. ± 1 digit (outside)
Calibration Check	automatic, at start-up	
Probe	stainless steel probe with penetration tip; 117 x dia 3.5 mm (4.6 x dia 0.14")	
Battery Type / Life	1.5V AA / approximately 25,000 hours of continuos use; auto-off after 8 minutes of non-use	
Environment	0 to 50°C (32 to 122°F); RH max 95%	
Dimensions	$165 \times 50 \times 20 \text{ mm} (6.5 \times 2.0 \times 0.8")$	
Weight	100 g (3.5 oz.)	

ORDERING INFORMATION

HI 151-00 (Checktemp®4 C) is supplied complete with battery and instructions

HI 151-01 (Checktemp®4 F) is supplied complete with battery and instructions

HI 151-001 (Checktemp®4 C) is supplied complete with calibration certificate, battery and instructions HI 151-011 (Checktemp®4 F) is supplied complete with calibration certificate, battery and instructions HI 151-02 (Checktemp®4 C) ±0.5°C accuracy, without CAL CHECK is supplied complete with battery and instructions



















